

Halton Hills Premier Gateway Project

Watercourse Photo Appendix B.1

Reach GOLF-001 (May 28, 2015)




Photo 1. Upper extent of reach, looking downstream.



Photo 2. Mid-reach, looking upstream.



Photo 3. Downstream portion of reach, looking upstream.



Photo 4. Downstream extent, looking downstream.

Reach GOLF-002 (May 28, 2015)



Photo 5. Upstream extent of the reach, looking upstream.



Photo 6. Upstream extent of the reach, looking downstream.



Photo 7. Cart path (on the downstream end), looking upstream.



Photo 8. Cart path (on the downstream end), looking downstream.




Photo 9. Downstream extent, looking upstream.

Reach GOLF-003 (May 28, 2015)



Photo 10. Upstream extent, looking downstream.



Photo 11. Mid reach, looking downstream.



Photo 12. Downstream extent (cart path), looking upstream.



Photo 13. Downstream extent (cart path) looking downstream.

Reach GOLF-004 (May 28, 2015)



Photo 14. Mid-reach, looking upstream – east branch.



Photo 15. Mid-reach, looking downstream – east branch.



Photo 16. Looking upstream towards western pond – west branch.



Photo 17. Looking downstream – west branch.

Reach HWY-001 (November 18, 2015)



Photo 18. Upstream extent, looking downstream of east channel.



Photo 19. Upstream extent, looking upstream from main channel.



Photo 20. Upstream extent, looking downstream of main channel.



Photo 21. View under bridge facing downstream of main channel.

Reach SIXTH-001 (November 18, 2015)



Photo 22. Upstream extent, looking upstream.



Photo 23. Upstream extent, looking downstream.



Photo 24. Downstream extent, looking upstream.



Photo 25. Downstream extent, looking downstream.

Reach STEELES-001 (May 28, 2015)



Photo 26. Upstream extent, looking upstream.



Photo 27. Mid- reach, looking downstream.



Photo 28. Mid-reach, looking upstream.

Reach STEELES-002 (May 28, 2015



Photo 29. Upstream extent, looking upstream.



Photo 30. Mid-reach, looking upstream.



Photo 31. Downstream extent, facing upstream.



Photo 32. Downstream extent, facing downstream, Steeles-002 (left) is converging with Steeles-003 (right).

Reach STEELES-003 (May 28, 2015)



Photo 33. Upstream extent, looking upstream.



Photo 34. Upstream extent, looking downstream.



Photo 35. Mid-reach, looking upstream.

Reach STEELES-004 (May 28, 2015)



Photo 36. Upstream extent, looking upstream.



Photo 37. Upstream extent, looking downstream.



Photo 38. Mid-reach, looking upstream.



Photo 39. Downstream extent, looking upstream.



Photo 40. Downstream extent, looking downstream.

Reach STEELES-005 (May 28, 2015)



Photo 41. Upstream extent, looking upstream.



Photo 42. Mid-reach, looking downstream.



Photo 43. Mid-reach, looking upstream.



Photo 44. Downstream extent, looking upstream.



Photo 45. Downstream, extent, looking downstream.

Reach TRAFALGAR-001 – CROSSING AT TRAFALGAR (May 28, 2015)



Photo 46. Looking upstream from road crossing.



Photo 47. Looking upstream at channel.



Photo 48. Looking downstream from road crossing.

Reach TRAFALGAR-002 (May 28, 2015)



Photo 49. Upstream extent, looking upstream.



Photo 50. Upstream extent, looking downstream.



Photo 51. Downstream extent, looking upstream.



Photo 52. Looking upstream from road crossing.



Photo 53. Looking downstream from road crossing (downstream extent).